

Shaft adapters



WDGWA10M06
Shaft adapter WDGWA10M06

for thru-bore and hollow bore (blind) encoder
Ø 10 mm
or couplings Ø 10 mm,
thread M6.



WDGWA10M08
Shaft adapter WDGWA10M08

for thru-bore and hollow bore (blind) encoder
Ø 10 mm
or couplings Ø 10 mm,
thread M8.



WDGWA10M10
Shaft adapter WDGWA10M10

for thru-bore and hollow bore (blind) encoder
Ø 10 mm
or couplings Ø 10 mm,
thread M10.



WDGWA10M12
Shaft adapter WDGWA10M12

for thru-bore and hollow bore (blind) encoder
Ø 10 mm
or couplings Ø 10 mm,
thread M12.



WDGWA10M14
Shaft adapter WDGWA10M14

for thru-bore and hollow bore (blind) encoder
Ø 10 mm
or couplings Ø 10 mm,
thread M14.



WDGWA10M16
Shaft adapter WDGWA10M16

for thru-bore and hollow bore (blind) encoder
Ø 10 mm
or couplings Ø 10 mm,
thread M16.



WDGWA10M20
Shaft adapter WDGWA10M20

for thru-bore and hollow bore (blind) encoder
Ø 10 mm
or couplings Ø 10 mm,
thread M20.